

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 107		Date yy mm dd 2024 11 13		
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Missoula MT 59808						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title Mechanical General Foreman Email matthew.olson@bnsf.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City DEER LODGE			Codes 0320		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County POWELL			C077		County						To Latitude			
Mile Post: From To				Inspection Point DEER LODGE SIDING						To Longitude				
Activity Code:	215	224	231	232	232X								CARS	
Units:	7	7	7	7	1								7	
Sub Units:	0	0	0	0	1								0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	FDDM	200553	FB	231	0144	B1				N	N	1	231

Description  
(B-end) coupler height less than 31 1/2" from top of rail.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	FDDM	200553	FB	231	0124	B1				N	N	1	231

Description  
(B-end) crossover platform bent to the point that it is unsafe.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No.	Report No.	Report Date
M3005	107	11/13/2024

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3										N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected one cut of cars for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	----------------------------------------	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
-------------------------------------------------------	-----------------------------------	----------------------------------------------	----------------------	----------------------	-------------------	----------------------	-------------------