

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave			Inspector's Signature			Inspector's ID No. M3003		Report No. 171		Date yy mm dd 2024 09 26			
Railroad/Company Name & Address BNSF RAILWAY COMPANY Laurel MT 59044						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Car Shop / Road Truck Foreman Email Signature _____				
						RR/Co. Code BNSF	Subdivision SYSTEM						
From: City LAUREL		Codes 0700		Destination City & County				Codes		From Latitude			
State MT		30		City						From Longitude			
County YELLOWSTONE		C111		County						To Latitude			
Mile Post: From To				Inspection Point LAUREL WEST T-3						To Longitude			
Activity Code:	224	229D	231										
Units:	1	1	1										
Sub Units:	0	0	0										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	6538	EMF	229	0119	C1			LAUREL WEST T-3	N	N	1	229D
Description Oil on left side walkway (2 larger spots).													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			