

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 114		Date yy mm dd 2025 08 11		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Car Shop / Road Truck Foreman Email Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City LAUREL			Codes 0700		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point LAUREL LOCOMOTIVE ROUND HOUSE						To Longitude				
Activity Code:		223	224	229D	MREC									
Units:		1	1	1	1									
Sub Units:		0	0	0	3									
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
1	BNSF	8069	EMF						LAUREL	N	N	0		
Description - [** Comment to Railroad/Company **] OTM (one time movement). Inspected BNSF 8069 post road grade crossing accident. Remove Grain from nose of locomotive & both rear walkways. Also confirm that the Non-Complying tags indicate the final destination as Alliance Nebraska. No other exceptions taken.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:					Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?				