

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel			Inspector's Signature			Inspector's ID No. M3005		Report No. 34		Date yy mm dd 2024 04 17			
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Helena MT 59601						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Kyle Patterson Title Mechanical Foreman Email kyle.patterson2@bnsf.com Signature _____				
						RR/Co. Code BNSF	Subdivision SYSTEM						
From: City HELENA			Codes 0590		Destination City & County				Codes	From Latitude			
State MT			30		City					From Longitude			
County LEWIS AND CLARK			C049		County					To Latitude			
Mile Post: From To					Inspection Point HELENA YARD					To Longitude			
Activity Code:	232T	LTM											
Units:	1	1											
Sub Units:	0	1											
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	LTM
Description - [** Comment to Railroad/Company **] Discussed Class I air brake observation, requirements and regulation with BNSF trainmaster.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:			Longitude:						
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code			Date(mm/dd/yyyy):				Comments on back?		