

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 4		Date yy mm dd 2020 01 13		
Railroad/Company Name & Address MONTANA RAIL LINK 2800 Shannon Road Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Mechanical Supervisor Email hpenninger@mtrail.com Signature _____				
						RR/Co. Code MRL		Subdivision SYSTEM						
From: City BILLINGS			Codes 0100		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point EXXON TANK FARM LOCKWOOD MT						To Longitude				
Activity Code:	215	224	231	232	232X	TCL							CARS	
Units:	30	30	30	30	1	25							30	
Sub Units:	0	0	0	0	0	0							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	518014	G	215	0301	A1			LOCKWOOD	N	N	1	215

Description
LEFT SIDE CAR I.D. NUMBER PAINTED OVER.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	HOMX	102097	T	231	0110	B1			LOCKWOOD	N	N	1	231

Description
HAND BRAKE INOPERATIVE, RELEASE LEVER STUCK IN THE RELEASE POSITION HAND BRAKE WILL NOT STAY APPLIED.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 4	Report Date 1/13/2020
-----------------------------	-----------------	--------------------------

Item 3	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC 232	Defect	Subrule	Speed	Class	Train #/Site LOCKWOOD	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code 232X
-----------	-------------------	-------------------	-----------	-----------------------	--------	---------	-------	-------	--------------------------	------------	------------	----------------------	--------------------------

Description - [** Comment to Railroad/Company **]

INSPECTED ONE CUT OF RAIL CARS FOR SECUREMENT OF UNATTENDED EQUIPMENT, NO EXCEPTIONS TAKEN.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
--	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	----------------------	-------------------	-------------------