

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 158		Date yy mm dd 2023 10 03		
Railroad/Company Name & Address BNSF RAILWAY COMPANY 107 1/2 N Sargent  Glendive MT 59330						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Gabriel Schlosser Title General Foreman Email gabriel.schlosser@bnsf.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City FORSYTH			Codes 0430		Destination City & County				Codes	From Latitude				
State MT			30		City					From Longitude				
County ROSEBUD			C087		County					To Latitude				
Mile Post: From To				Inspection Point FORSYTH RAIL YARD						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	40	45	5	45	40	5							40	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	5091	EMF	229	0093	C1			FORSYTH YARD	N	N	1	229D
Description Right side emergency fuel shut off decal faded out not readable.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	6203	EMF	229	0093	C1			FORSYTH YARD	N	N	1	229D
Description Left side emergency fuel shut off decal faded out not readable.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		

**DEPARTMENT OF TRANSPORTATION**  
FEDERAL RAILROAD ADMINISTRATION (FRA)

**INSPECTION REPORT**  
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 158	Report Date 10/3/2023
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	6203	EMF	229	0045	C1			FORSYTH YARD	N	N	1	229D

Description  
Number (6) Traction motor lead cables covered in oil.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	CEFX	71353	CH	215	0301	A1			FORSYTH YARD	N	N	1	215

Description  
Left side car I.D. not readable.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	TILX	54469	CH	215	0301	A1			FORSYTH YARD	N	N	1	215

Description  
Left side car I.D. not readable.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------