

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

| | | | | | | | | | | | | | | |
|---------------------------------------------------------|-----|-----|------------|------------------------------------------------|---------------------------|---------------------|-----------------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------|--------------------------------|--|--|
| Inspector's Name Jackson, Dave | | | | Inspector's Signature | | | | Inspector's ID No. M3003 | | Report No. 187 | | Date yy mm dd 2023 11 16 | | |
| Railroad/Company Name & Address BNSF RAILWAY COMPANY | | | | | | R/C R | Division SYSTEM | | RR/Co. Representative (Receipt Acknowledged) Name Matthew Krick Title Mechanical Foreman Email matthew.krick@bnsf.com Signature _____ | | | | | |
| | | | | | | RR/Co. Code BNSF | Subdivision SYSTEM | | | | | | | |
| | | | | | | | | | | | | | | |
| From: City WORDEN | | | Codes 1302 | | Destination City & County | | | | Codes | | From Latitude | | | |
| State MT | | | 30 | | City | | | | | | From Longitude | | | |
| County YELLOWSTONE | | | C111 | | County | | | | | | To Latitude | | | |
| Mile Post: From To | | | | Inspection Point POMPEYS PILLAR YELLOWSTONE CO | | | | | | To Longitude | | | | |
| Activity Code: | 215 | 224 | 229D | 231 | 232 | SAX | | | | | | CARS | | |
| Units: | 25 | 26 | 1 | 26 | 25 | 1 | | | | | | 25 | | |
| Sub Units: | 0 | 0 | 0 | 0 | 0 | 1 | | | | | | 0 | | |

| | | | | | | | | | | | | | |
|------|-------------------|-------------------|-----------|-------------|--------|---------|-------|-------|----------------|-------|-------|--------------|---------------|
| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/ USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
| 1 | BNSF | 5755 | EMF | 229 | 0045 | B5 | | | POMPEYS PILLAR | N | N | 1 | 229D |

Description
Toilet drain leaking product onto L-1 Brake cylinder & rigging.

| | | | | | | | |
|--------------|--|--------------|--|--------------|--|----------|--|
| Seal Applied | | Seal Removed | | Hazard Class | | UN/NA ID | |
| | | | | | | | |

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

| | | | | | | | | | | | | | |
|------|-------------------|-------------------|-----------|-------------|--------|---------|-------|-------|----------------|-------|-------|--------------|---------------|
| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/ USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
| 2 | BNSF | 5755 | EMF | 229 | 0067 | A1 | | | POMPEYS PILLAR | N | N | 1 | 229D |

Description
Left / Rear Horizontal shock leaking hydraulic oil.

| | | | | | | | |
|--------------|--|--------------|--|--------------|--|----------|--|
| Seal Applied | | Seal Removed | | Hazard Class | | UN/NA ID | |
| | | | | | | | |

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|-----------------------------|-------------------|---------------------------|
| Inspector's ID No. M3003 | Report No. 187 | Report Date 11/16/2023 |
|-----------------------------|-------------------|---------------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|----------------|-------|-------|--------------|---------------|
| 3 | BN | 535015 | H | 215 | 0103 | A1 | | | POMPEYS PILLAR | N | N | 1 | 215 |

Description
R-2 Flange @ FRA limits 7/8 inch.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---------------------------------------------------------------------|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---------------------------------------------------------------------|-----------|------------|

| | | | | | | |
|----------------------------------------------------|--------------------------------------------------------------------------------|----------------------|----------------------|-------------------|----------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | <input type="text"/> | Date(mm/dd/yyyy): | <input type="text"/> | Comments on back? |
|----------------------------------------------------|--------------------------------------------------------------------------------|----------------------|----------------------|-------------------|----------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|----------------|-------|-------|--------------|---------------|
| 4 | BN | 534924 | H | 215 | 0301 | A1 | | | POMPEYS PILLAR | N | N | 1 | 215 |

Description
Right side car ID partly covered / obstructed by reflective sheeting.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---------------------------------------------------------------------|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---------------------------------------------------------------------|-----------|------------|

| | | | | | | |
|----------------------------------------------------|--------------------------------------------------------------------------------|----------------------|----------------------|-------------------|----------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | <input type="text"/> | Date(mm/dd/yyyy): | <input type="text"/> | Comments on back? |
|----------------------------------------------------|--------------------------------------------------------------------------------|----------------------|----------------------|-------------------|----------------------|-------------------|