

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name <b>Blackwell, Michael</b>				Inspector's Signature				Inspector's ID No. <b>11265</b>		Report No. <b>154</b>		Date yy mm dd <b>2024 10 02</b>	
Railroad/Company Name & Address <b>BNSF RAILWAY COMPANY</b>  <b>Laurel MT</b>						R/C <b>R</b>		Division <b>SYSTEM</b>		RR/Co. Representative (Receipt Acknowledged) Name <b>Harlen Penninger</b> Title <b>General Foreman Mechanical</b> Email <b>hpenninger@bnsf.com</b> Signature _____			
						RR/Co. Code <b>BNSF</b>		Subdivision <b>SYSTEM</b>					
From: City <b>FORSYTH</b>			Codes <b>0430</b>		Destination City & County				Codes		From Latitude		
State <b>MT</b>			<b>30</b>		City						From Longitude		
County <b>ROSEBUD</b>			<b>C087</b>		County						To Latitude		
Mile Post: From To				Inspection Point <b>BNSF FORSYTH YARD</b>						To Longitude			
Activity Code:	<b>215</b>	<b>231</b>	<b>232</b>	<b>224</b>	<b>229D</b>	<b>223</b>	<b>232X</b>	<b>MREC</b>				<b>CARS</b>	
Units:	<b>12</b>	<b>16</b>	<b>16</b>	<b>16</b>	<b>4</b>	<b>4</b>	<b>1</b>	<b>4</b>				<b>12</b>	
Sub Units:	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>4</b>	<b>8</b>				<b>0</b>	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
<b>1</b>	<b>BNSF</b>	<b>8508</b>	<b>EMF</b>	<b>229</b>	<b>0021</b>	<b>A3</b>			<b>FORSYTH YARD</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>MREC</b>

Description  
Daily inspection report missing from the cab.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
<b>2</b>	<b>BNSF</b>	<b>8508</b>	<b>EMF</b>	<b>229</b>	<b>0093</b>	<b>C1</b>			<b>FORSYTH YARD</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>229D</b>

Description  
Left side fuel line safety cut-off device improperly marked.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 11265	Report No. 154	Report Date 10/2/2024
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	8368	EFG	229	0119	C1			FORSYTH YARD	N	N	1	229D

Description  
Passageways floors hazardous, oil on left walkway.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	8368	EFG	229	0045	C1			FORSYTH YARD	N	N	2	229D

Description  
Excessive accumulation of oil on electrical equipment, oil leak on electric drive motor and oil leaking on the main generator.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	GN	78498	G	231	0130	A3			FORSYTH YARD	N	N	1	231

Description  
(AL) Sill step loose.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	GN	78498	G	231	0134	A3			FORSYTH YARD	N	N	1	231

Description  
(BL) Side ladder loose.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. 11265	Report No. 154	Report Date 10/2/2024
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7				232					FORSYTH YARD	N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected four cuts of locomotives and cars for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	--	----------------------	----------------------	-------------------	----------------------	-------------------