

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 43		Date yy mm dd 2025 03 13		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Car Shop / Road Truck Foreman Email Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City LAUREL			Codes 0700		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point LAUREL WEST TRACK-2						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	120	123	3	123	120	1							120	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	5999	EMF	229	0045	F2			G-MITTAC9-09M	N	N	1	229D

Description
Left side car body door ladder loose, (2) bolts not installed.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	7000	EMF	229	0067	A1			G-MITTAC9-09M	N	N	2	229D

Description
L-6 & R-1 Shocks leaking hydraulic oil.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 43	Report Date 3/13/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	7000	EMF	229	0045	A4			G-MITTAC9-09M	N	N	1	229D

Description

Left front weight management stop collar broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	474638	CH	215	0301	A1			G-MITTAC9-09M	N	N	1	215

Description

Left side build date painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	BNSF	474830	CH	215	0117	E1			G-MITTAC9-09M	N	N	4	215

Description

R-1, R-2, R-3 & R-4 Roof liners are shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	BNSF	478946	CH	232	0103	F3			G-MITTAC9-09M	N	N	1	232

Description

L-1 Brake shoe worn to the backing plate / beam.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 43	Report Date 3/13/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	COER	320927	CH	224	0103	C			G-MITTAC9-09M	N	N	1	224

Description

Left side retroreflective sheeting painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	BNSF	476585	CH	215	0117	E1			G-MITTAC9-09M	N	N	1	215

Description

R-3 Roof liner shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	BNSF	483011	CH	215	0117	E1			G-MITTAC9-09M	N	N	1	215

Description

L-1 Roof liner shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	BNSF	483011	CH	215	0117	E1			G-MITTAC9-09M	N	N	1	215

Description

L-1 Roof liner shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 43	Report Date 3/13/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	NOKL	852195	CH	224	0103	C			G-MITTAC9-09M	N	N	1	224

Description
Right side retroreflective sheeting painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	NOKL	852195	CH	215	0301	A1			G-MITTAC9-09M	N	N	1	215

Description
Right side build date painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13	BNSF	474056	CH	215	0117	E1			G-MITTAC9-09M	N	N	3	215

Description
L-1, L-2 & L-3 Roof liners are shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
14	BNSF	498036	CH	215	0103	A1			G-MITTAC9-09M	N	N	1	215

Description
R-3 Wheel flange @ FRA limits 7/8 inch.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 43	Report Date 3/13/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
15	BNSF	472788	CH	215	0301	A1			G-MITTAC9-09M	N	N	1	215

Description

Left side build date painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
16	FURX	818523	CH	215	0301	A1			G-MITTAC9-09M	N	N	1	215

Description

Right side build date painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
17	FURX	818523	CH	215	0117	E1			G-MITTAC9-09M	N	N	2	215

Description

R-2 & R-4 Roof liners are shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
18	BNSF	480748	CH	215	0117	E1			G-MITTAC9-09M	N	N	4	215

Description

R-1, R-2, R-3 & R-4 Roof liners are shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 43	Report Date 3/13/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
19	BNSF	480162	CH	215	0117	E1			G-MITTAC9-09M	N	N	1	215

Description
L-1 Roof liner are shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
20	BNSF	430444	CH	224	0103	C			G-MITTAC9-09M	N	N	1	224

Description
Right side retroreflective sheeting painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
21				232					G-MITTAC9-09M	N	N	0	232

Description - [** Comment to Railroad/Company **]
Inspected W/B Grin train for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------