

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 76		Date yy mm dd 2025 04 30		
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Car Shop / Road Truck Foreman Email Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City LAUREL			Codes 0700		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point LAUREL WEST T-3						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	55	57	2	57	55	1							55	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	7284	EMF	229	0093	C1			LAUREL WEST T-3	N	N	1	229D
Description Left side emergency fuel shut off decal faded out.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	7284	EMF	229	0045	A4			LAUREL WEST T-3	N	N	1	229D
Description Air dryer drain hose bent blocking air / water flow.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?	

**DEPARTMENT OF TRANSPORTATION**  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 76	Report Date 4/30/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	5203	EMF	229	0067	A1			LAUREL WEST T-3	N	N	1	229D

Description  
R-1 & R-3 Vertical shocks leaking hydraulic oil.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	5203	EMF	229	0045	C1			LAUREL WEST T-3	N	N	1	229D

Description  
Oil on generator.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	GATX	225982	T	232	0103	F3			LAUREL WEST T-3	N	N	1	232

Description  
L-2 Brake shoe broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	GBRX	707216	T						LAUREL WEST T-3	N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
R-3 Wheel flange @ AAR limits 15/16".

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT  
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No.	Report No.	Report Date
M3003	76	4/30/2025

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7				232					LAUREL WEST T- 3	N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected W/B train set for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	-----------------------------------	--	----------------------	----------------------	-------------------	----------------------	-------------------