

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 13		Date yy mm dd 2023 03 14		
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Havre MT						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged)				
						RR/Co. Code BNSF		Subdivision SYSTEM		Name Christopher Romero				
						Title Zone Superintendent								
						Email christopher.romero@BNSF.com								
Signature														
From: City HAVRE			Codes 0580		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County HILL			C041		County						To Latitude			
Mile Post: From To				Inspection Point HAVRE DIESEL SHOP						To Longitude				
Activity Code:	229D	224	231	232X										
Units:	6	6	6	1										
Sub Units:	0	0	0	2										

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	5203	EMF	229	0093	C1			NORTH 5	N	N	1	229D

Description  
Both left and right-side emergency fuel cut off decals faded/illegible.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	6857	EMF	229	0067	C4			NORTH 5	N	N	1	229D

Description  
(R4) distributed weight management pin missing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT  
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No.	Report No.	Report Date
M3005	13	3/14/2023

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3										N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected 2 locomotive consists for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	-----------------------------------	--	----------------------	----------------------	-------------------	----------------------	-------------------