

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel			Inspector's Signature			Inspector's ID No. M3005		Report No. 33		Date yy mm dd 2024 04 15		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Havre MT					R/C R RR/Co. Code BNSF	Division SYSTEM Subdivision SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Christopher Romero Title Zone Superintendent Email christopher.romero@BNSF.com Signature _____				
From: City HAVRE		Codes 0580		Destination City & County				Codes		From Latitude		
State MT		30		City						From Longitude		
County HILL		C041		County						To Latitude		
Mile Post: From To				Inspection Point HAVRE DIESEL SHOP					To Longitude			
Activity Code:	229D	231	232X									
Units:	6	6	1									
Sub Units:	0	0	3									

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	5257	EMF	229	0045	C1				N	N	1	229D

Description
Excessive accumulation of oil on high voltage electrical cables. In front of fuel tank on conductors side.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	5257	EMF	229	0045	B2				N	N	1	229D

Description
(Conductors side) oil on walkway.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3005	Report No. 33	Report Date 4/15/2024
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3										N	N	0	

Description - [** Comment to Railroad/Company **]

Inspected three shop released locomotives, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4										N	N	0	

Description - [** Comment to Railroad/Company **]

Inspected 4 locomotive consists for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------