

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 23		Date yy mm dd 2023 04 05		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Great Falls MT						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name David Johnson Title Mechanical Foreman Email david.johnson122807@bnsf.com Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City BUTTE			Codes 0180		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County SILVER BOW			C093		County						To Latitude			
Mile Post: From To				Inspection Point BUTTE YARD						To Longitude				
Activity Code:	215	224	229D	231	232	232X	LTM						CARS	
Units:	10	13	3	13	10	4	1						10	
Sub Units:	0	0	0	0	0	1	2						0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	552162	F	232	0103	F3			BUTTE YARD	N	N	1	232
Description Vent protector broken.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	914002	G	232	0103	F3			BUTTE YARD	N	N	1	232
Description (L4) brake shoe worn to backing plate.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3005	Report No. 23	Report Date 4/5/2023
-----------------------------	------------------	-------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	SMW	738522	FB	232	0103	F3			BUTTE YARD	N	N	1	232

Description
(R4) brake shoe worn to backing plate.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4									BUTTE YARD	N	N	0	232X

Description - [** Comment to Railroad/Company **]
Inspected three cuts of cars and one locomotive consist for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------