

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 36		Date yy mm dd 2023 05 18		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Great Falls MT						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name David Johnson Title Mechanical Foreman Email david.johnson122807@bnsf.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City GREAT FALLS			Codes 0530		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County CASCADE			C013		County						To Latitude			
Mile Post: From To				Inspection Point GREAT FALLS ROUNDHOUSE						To Longitude				
Activity Code:	224	229D	231	232X	LTM									
Units:	5	5	5	3	4									
Sub Units:	0	0	0	1	1									

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	2893	EMF	229	0045	C1				N	N	1	229D

Description
Excessive accumulation of oil on electrical equipment - Oil leaking on traction motor leads behind fuel tank.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	7929	EMF	229	0045	A4				N	N	0	229D

Description - [** Comment to Railroad/Company **]
#1 traction motor lead support bracket missing bolt/loose bolt.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No.	Report No.	Report Date
M3005	36	5/18/2023

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3										N	N	0	232X

Description - [** Comment to Railroad/Company **]

Inspected three locomotive consists for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	-----------------------------------	--	----------------------	----------------------	-------------------	----------------------	-------------------