

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 151		Date yy mm dd 2022 10 04			
Railroad/Company Name & Address MONTANA RAIL LINK 2800 Shannon Road  Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Mark Turner Title General Mechanical Foreman Email mturner@mtrail.com Signature _____					
						RR/Co. Code MRL		Subdivision SYSTEM							
From: City LAUREL			Codes 0700		Destination City & County				Codes		From Latitude				
State MT			30		City						From Longitude				
County YELLOWSTONE			C111		County						To Latitude				
Mile Post: From To				Inspection Point LAUREL ROUNDHOUSE								To Longitude			
Activity Code:	224	229D	232X	231											
Units:	1	1	2	1											
Sub Units:	0	0	2	0											

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	8332	EMF	231	0138	C2				N	N	1	231

Description  
 Left front plow hand rail insufficient clearance.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:		Longitude:	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div>		Date(mm/dd/yyyy): <div style="border: 1px solid black; width: 80px; height: 15px; display: inline-block;"></div> Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	MRL	1104	C							N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
 Inspected remote control caboose valves, braking and radio systems. No exceptions taken

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:		Longitude:	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div>		Date(mm/dd/yyyy): <div style="border: 1px solid black; width: 80px; height: 15px; display: inline-block;"></div> Comments on back?	

**DEPARTMENT OF TRANSPORTATION**  
FEDERAL RAILROAD ADMINISTRATION (FRA)

**INSPECTION REPORT**  
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 151	Report Date 10/4/2022
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3										N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected 1 locomotive for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---------------------------------------------------------------------	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
----------------------------------------------------	--------------------------------------------------------------------------------	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4										N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected 1 caboose for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---------------------------------------------------------------------	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
----------------------------------------------------	--------------------------------------------------------------------------------	----------------------	----------------------	-------------------	----------------------	-------------------