

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 135		Date yy mm dd 2023 08 31		
Railroad/Company Name & Address MONTANA RAIL LINK 2800 Shannon Road Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Mark Turner Title General Mechanical Foreman Email mturner@mtrail.com Signature _____				
						RR/Co. Code MRL		Subdivision SYSTEM						
From: City LAUREL			Codes 0700		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point LAUREL WEST TRACK 3						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	110	113	3	113	110	1							110	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	5290	EMF	229	0119	C1			U-FYNAWAO-14T	N	N	1	229D
Description Oil on left walkway.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	5290	EMF	229	0093	C1			U-FYNAWAO-14T	N	N	2	229D
Description Both Left & Right sides emergency fuel shut off decals faded out damaged, not fully readable.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 135	Report Date 8/31/2023
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	5290	EMF	229	0093	C1			U-FYNAWAO-14T	N	N	1	229D

Description
Right side emergency fuel shut off decal faded out damaged, not fully readable.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	CBTX	721619	T	232	0103	F3			U-FYNAWAO-14T	N	N	1	232

Description
R-3 Brake shoe partly broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5				232					U-FYNAWAO-14T	N	N	0	232X

Description - [** Comment to Railroad/Company **]
Inspected W/B "Oil Train" for securement of unattended equipment, no exceptions taken.
Haz-Mat 1267 Crude Oil

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------