

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Gehrke, Howard A.		Inspector's Signature		Inspector's ID No. 31030		Report No. 99		Date yy mm dd 2023 12 12					
Railroad/Company Name & Address MONTANA RAIL LINK 1655 Rodgers St. Missoula Missoula MT 59634				R/C R RR/Co. Code MRL	Division SYSTEM Subdivision SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title General Foreman Email molson@mtrail.com Signature _____						
From: City MISSOULA		Codes 0830		Destination City & County			Codes		From Latitude				
State MT		30		City					From Longitude				
County MISSOULA		C063		County					To Latitude				
Mile Post: From To				Inspection Point MISSOULA CAR SHOP				To Longitude					
Activity Code:	232X	MREC	LTM	218M	218O								
Units:	1	1	1	1	1								
Sub Units:	1	250	12	2	1								
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] Reveiwed of records for Trains U-RBOLAU0-11T and J-NEWINB9-10A. Life Tip with MRL Carmen. No defects noted.													
Seal Applied		Seal Removed		Hazard Class				UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			