

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Gehrke, Howard A.				Inspector's Signature				Inspector's ID No. 31030		Report No. 57		Date yy mm dd 2024 07 01		
Railroad/Company Name & Address BNSF - Havre 1655 Rogers St. Missoula MT 59634						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title General Manager Email Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City MISSOULA			Codes 0830		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County MISSOULA			C063		County						To Latitude			
Mile Post: From To				Inspection Point YARD TRACKS (SHOP RELEASES)						To Longitude				
Activity Code:	232X	232	231	215	224	218M							CARS	
Units:	1	7	7	7	7	1							7	
Sub Units:	3	0	0	0	0	1							0	
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
1	NCUX	11215	H	232	0103	F3			YARD TRACK	N	N	1	232	
Description A-end angle cock will not lock into place.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:						
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?				