

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Gehrke, Howard A.				Inspector's Signature				Inspector's ID No. 31030		Report No. 112		Date yy mm dd 2025 12 10		
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1655 Rodgers St.  Missoula MT 59808						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title General Foreman Email Matthew.Olson@BNSF.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City MISSOULA			Codes 0830		Destination City & County				Codes	From Latitude				
State MT			30		City					From Longitude				
County MISSOULA			C063		County					To Latitude				
Mile Post: From To				Inspection Point MISSOULA YARD (MOW CARS)					To Longitude					
Activity Code:	232X	232	231	215	224	MREC	LTM	218M				CARS		
Units:	1	21	21	21	21	1	1	1				21		
Sub Units:	2	0	0	0	0	1	4	1				0		
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
1	BNSF	927203	G	232	0103	F3			YARD TRACK	N	N	2	232	
Description R-2 brake shoe worn to backing plate. R-3 brake shoe worn to backing plate.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <input type="text"/> <input type="text"/> <input type="text"/>			Date(mm/dd/yyyy): <input type="text"/>		Comments on back?			