

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Voigt, Jordan		Inspector's Signature			Inspector's ID No. M3004		Report No. 29		Date yy mm dd 2022 03 29				
Railroad/Company Name & Address MONTANA RAIL LINK Missoula MT					R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title Mechanical Foreman Email Signature _____					
					RR/Co. Code MRL	Subdivision SYSTEM							
From: City MISSOULA		Codes 0830		Destination City & County				Codes		From Latitude			
State MT		30		City						From Longitude			
County MISSOULA		C063		County						To Latitude			
Mile Post: From To				Inspection Point MISSOULA REPAIR TRACK					To Longitude				
Activity Code:	215	224	231	232	232X						CARS		
Units:	18	18	18	18	1						18		
Sub Units:	0	0	0	0	2						0		
Item 1	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code
Description - [** Comment to Railroad/Company **] Inspected two cuts of rip releases, no exceptions taken.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?		